BUTANE PENCIL TORCH

Model 94185

INSTRUCTIONS AND PRECAUTIONS

Visit our website at:
http://www.harborfreight.com

SAVE THESE INSTRUCTIONS. READ ALL PRECAUTIONS AND INSTRUCTIONS.

Copyright© 2006 by Harbor Freight Tools®. All rights reserved. No portion of this document or any artwork contained herein may be reproduced in any shape or form without the express written consent of Harbor Freight Tools. Diagrams within this document may not be drawn proportionally. Due to continuing improvements, actual product may differ slightly from the product described herein. Tools required for assembly and service may not be included.

For technical questions or replacement parts, please call 1-800-444-3353.

Manual Revised 10a

SPECIFICATIONS

Flame Temperature	2000° F
Fuel Type	Butane
Burn Time	up to 15 minutes

UNPACKING

When unpacking, make sure that the item is intact and undamaged. If any parts are missing or broken, please call Harbor Freight Tools at 1-800-444-3353 as soon as possible.

IMPORTANT SAFETY INFORMATION

1. Wear ANSI-approved safety goggles and heavy-duty work gloves during assembly.
2. Use only with butane fuel.
3. Do not aim Pencil Torch at yourself, others or animals.
4. Do not aim at flammable materials.
5. Keep hands and fingers away from path of flame and from hot tip.
6. The brass components of this product contain lead, a chemical known to the State of California to cause birth defects (or other reproductive harm). (California Health & Safety code § 25249.5, *et seq.*)
7. Use as intended only. Do not modify or use for purpose for which is was not intended.
8. Keep away from children. This product is not a toy. Do not allow children to play with or near this item.
9. Inspect before every use; do not use if parts are loose or damaged. If gas odor is detected during use, immediately shut off Pencil Torch. Extinguish all open flames and, once

cooled, check all connections for gas leaks.

10. Turn off after every use. Allow Pencil Torch to cool completely before storing.

11. Do not store any flammable liquids or materials in area surrounding Pencil Torch or work area.

12. Store Pencil Torch in a dry, safe location out of reach of children.

13. Maintain product labels and nameplates. These carry important safety information. If unreadable or missing, contact Harbor Freight Tools for a replacement.

OPERATION

Read the ENTIRE IMPORTANT SAFETY INFORMATION section at the beginning of this document including all text under subheadings therein before set up or use of this product.

Note: Torch is supplied empty for safety reasons.

1. Rotate the Brass Valve counterclockwise fully to the OFF position.

2. Turn the torch so that the fill port is on top. Add butane fuel to the fill port. **Only use butane fuel with this product!** The Torch will fill with fuel in about five seconds.

3. Wipe off any spilled fuel with a cloth, put away the butane fuel, and allow the butane fuel inside the torch to stabilize for about 5 minutes before operating.

4. To light Pencil Torch, tilt the tip upward slightly, but away from your face and any flammable objects, and turn the Brass Valve clockwise to "ON". Listen for the sound of flowing gas. **Be careful to keep fingers away from the path of the flame.** Move a lit match flame to the tip to ignite the Torch. Once lit, the size of the flame can be adjusted by rotating the Brass Valve.

5. To turn off, rotate the Brass Valve counterclockwise fully to the OFF position.

6. When done using this product, allow it to completely cool down, and store it in a safe location that is out of reach of children.

Note: Replacement parts are not available for this item. Discard and do not use if leaking, damaged, parts are missing.